#### ELECTRONIC TRANSMISSION

### IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patent No. : 7,892,469 B2 Confirmation No. : 3564

Inventors : Florencia Lim et al. Issued : February 22, 2011

Art Unit : 1744

Examiner : Edmund H. Lee

Title : METHOD OF MAKING A NON-COMPLAINT BALLOON FOR A CATHETER

Docket No.: : ACSC 68062

Customer No. : 24201

REQUEST FOR CERTIFICATE OF CORRECTION

Certificate of Corrections Branch Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Dear Sir:

The above-identified patent application file has been found to have the errors set forth in the enclosed Certificate of Correction. It is requested that a Certificate of Correction be issued and returned to us. Since the errors occurred in the final printing phase of the patent, no fee is enclosed. However, should the Office determine that a fee is required, please charge our Deposit Account No. 06-2425.

The errors are verifiable in the patent application file as follows:

# ERROR VERIFICATION

Drawing page, Sheet 3 of 3, delete current PTO error. See Amendment dated 10/8/07 at

## **ERROR**

### VERIFICATION

page and insert instead replacement Sheet 3 of 3.

page 2 with attachment.

Column 11, line 13, after "300" insert --psi--.

PTO error. See application at page 25.

We respectfully request that the Certificate of Correction be expeditiously issued since the errors reported herein were incurred through the fault of the United States

Patent and Trademark Office. This document is being transmitted electronically.

Attached hereto is Form PTO/SB/44 which is suitable for printing.

This document is being transmitted electronically.

Date: January 30, 2012 Respectfully submitted,

FULWIDER PATTON LLP

By: /Thomas H. Majcher/

Thomas H. Majcher, Registration No. 31,119

THM:he

FULWIDER PATTON LLP Howard Hughes Center 6060 Center Drive, Tenth Floor Los Angeles, CA 90045 Telephone: (310) 824-5555 Facsimile: (310) 824-9696 Customer No. 24201